



	91-60190-02	NSA	STARTING CONTROL BOX ASSY 230/1/50HZ - INCLUDES:	1
5	58-60493-01	PL*	EMPTY BOX	1
10	68-61480-00	PL*	BRACKET	1
15	58-60298-01		GROMMET	1
20	22-60568-01	PL*	HARNESS - INCLUDES:	1
NS	22-60254-01SK		C1 CONNECTOR 1 WAY (MATES WITH 22-60254-00SK)	1
NS	22-60254-05SK		CONNECTOR 2 WAYS (MATES WITH 22-60254-04SK)	1
25	10-00424-00		RELAY, 230/1/50HZ	1
30	34-01184-54	PL*	NUT, LOCK M4	1
35	34-60095-04	PL*	WASHER, LOCK M4 X 5MM	1
40	10-60048-03		CS1 CS2 CAPACITOR, 260/325V 150MFD	2
46	34-60002-54	PL*	WASHER, M4	3
60	22-60397-02		RESISTOR, 3W 15 KOHMS	1
65	10-60047-04		CP CAPACITOR, 450V 30MFD	1
100	62-60863-00	NSI	DECAL	1
105	62-03957-01		DECAL, WARNING HIGH VOLTAGE	1
115	62-60408-07	NSI	DECAL, VOLTAGE 230/1/50HZ	1
120	67-60177-00	PL*	BRACKET	1
125	34-60089-05	PL*	NUT, LOCK M5	4
150	34-60068-20		SCREW, M6 X 20MM	9